


## Anschluss Drehstrommotor über Klemmenblock

Three Phase motor means of CAGE CLAMP®

Raccordement du moteur triphasé sur le bornier élastique



|   | IEC / EN<br>60034-8                                     | NEMA<br>MG 1   | Farbe  | Colour                  | Couleur  |
|---|---|----------------|--|-------------------------|--|
| Netzanschluss<br>Supply lines<br>Branchement réseau | L1<br>L2<br>L3  | L1<br>L2<br>L3 |  |                         |  |
| Motorwicklung<br>Motor winding                      | U1<br>V1<br>W1  | T1<br>T2<br>T3 | schwarz<br>blau<br>braun                                   | black<br>blue<br>brown  | noir<br>bleu<br>marron                               |
| Bobinage du moteur                                  | U2<br>V2<br>W2  | T4<br>T5<br>T6 | gelb<br>rot<br>violett                                     | yellow<br>red<br>violet | jaune<br>rouge<br>violet                             |
| Δ   | Schaltung für niedrige<br>Nennspannung<br>(z.B.: 230 V) |                | Connections for the<br>low rated voltage<br>(e.g.: 230 V)  |                         | Couplage basse<br>tension nominale<br>(230 V p. ex.) |
| Y   | Schaltung für hohe<br>Nennspannung<br>(z.B.: 400 V)     |                | Connections for the<br>high rated voltage<br>(e.g.: 400 V) |                         | Couplage haute<br>tension nominale<br>(400 V p. ex.) |